

- NOTES: 1. The principal aim is to check that every wire is connected to the 9-way socket including the 10M between pin 1 and the socket frame.
  - 2. For the serial port to work, both CTS and DCD must be high.

FIGURE A.2 RS232 LOOPBACK TEST PLUG